

2024/2025 RIPPLE winter works activity so far this year

Despite the horrendous weather we've been having, the team have been out braving the cold and rain to crack on with some much-needed work. See below to see some of the fantastic jobs they've been doing.

Pavenham - FP13 approach (unregistered land) a fallen tree that was blocking the path was cleared and the area tidied.



Area after fallen tree removal



Roxton - FPA1 low overhanging branches and vegetation was cut back allowing more light in to help dry out and improve surface and also a huge improvement to the walking area.



Before



After

Clapham – Several marker posts were replaced, relocated and re-set at various locations throughout the Parish, providing walkers and ramblers with clear and defined routes.



Renhold – Cutting back and clearance of vegetation at ditch crossing.



And clearing up around the fingerposts at Wilden Road



Chellington – Clearance of vegetation and removal of low hanging branches and brambles at Footpath A9



Before



After



Before



After



Before



After



Before



After

Bromham and Stagsden— The footpaths were cut back and cleared the Bridleway widened and improved



Before



After



Before



After

Oakley Hill– A new Bridleway created.



Stevington– Footpaths FP15 and FP 8 new marker posts installed and new direction disks added along the route



Thurleigh– New marker posts installed and new direction disks added along the route



Sharnbrook– Marker posts installed and new direction disks added along the route, brambles cut back from path.

